


SAFETY BULLETIN

Your customer deserves quality, dependable service.



In an effort to drastically reduce costs some repair facilities will re-use scrap obsolete parts when repairing your elevator control valves.

The picture to the left shows a “rebuilt” valve from an independent repair facility. Please note the following **obsolete parts** were **reused** in the process:

- Control blocks (up and down)
- Solenoid assemblies
- Leveling speed regulator
- Piston and guide assemblies *

* This Down Piston Assembly reused an old style, obsolete piston rod. If stressed or over-torqued, serious consequences could result.

The same quality and workmanship that goes into the production of our new products is carried over into the repair service we provide. All valves we receive for repair are brought up to current production standards and *obsolete scrap parts are placed where they belong.*

Don't risk it – have the piece of mind in knowing that your Maxton valve is being serviced with the same high quality standards that we put into all we do.



Visit our website @ www.maxtonvalve.com and complete our online 'Returned Goods Form' to get the quality repair services you and your customer deserve or contact our sales dept. at 775-782-1700.